

Sanitized - Approved For Release : CIA-RDP71B00263R000100180002-8

DATE

~~SECRET~~

1	DM	9
2		10
3		11
4	IDEA	12
5		13
6		14
7		15
8		16

TO

FROM

ACTION

INFO

IN 78755

Handwritten signature

05A1-20

TO

INFO

CITE

~~SECRET~~ 061749Z CITE [REDACTED] 0793 25X1A6c

PRIORITY [REDACTED] INFO PRIORITY [REDACTED] 25X1A6c 25X1A6c

[REDACTED] IDEALIST/SCOPE SAFI/LOGS 25X1A2g

REF: [REDACTED] 0079 25X1A6c

1. PROBLEM EXPERIENCED IN REF RECALLS THAT AT ONE TIME SYS 9 VIDEO, SYS 12 VIDEO, AND CONTINUOUS BW WERE WIRED TOGETHER FOR RECORDING. A CHECK SHOULD BE MADE TO INSURE OF NO SHORT BETWEEN PIN 2 AND PIN 3 OF P1 ON MC RECORDER.

2. ON MC RECORDER DRAWING RS54 WIRE SV144B22 SHOULD BE STOWED. IT MAY STILL BE CONNECTED, OR IN RH CONSOLE IS TERMINAL AT WHICH CONVECTION WAS MADE, CHECK WIRE SV144E22.

~~SECRET~~ TOR: 061833Z JUNE 67

~~SECRET~~

GROUP 1
EXCLUDED FROM AUTO-
MATIC DOWNGRADING
AND DECLASSIFICATION